



Source of Elevation: Bench Mark Rt. 10, 1/2 mile North East. 726'
 Error of Closure 1/1006

- Fracture Before 6/5/29
 - New Location
 - Drill Deeper
 - Redrill
 - Abandonment
- 6-26-74

I, the undersigned, hereby certify that this map is correct to the best of my knowledge and belief and shows all the information required by Paragraph 5 of the Rules and Regulations of the Oil and Gas Section of the Mining Laws of West Virginia.

The accuracy of this survey is within the limits and as prescribed in Paragraph 5 by the Oil and Gas Division of the Department of Mines Regulations.

Robert X. Judd

CARL MORE'S
 Company W. Va. Department of Mines, Oil and Gas Div.
Box 288 - Gauntsville, W. Va.
 Address 1204 Kanawha Blvd. E. Charleston, W. Va. 25301
 Farm Donald and Kathy Ullum
 Tract _____ Acres 20 1/2 Lease No. _____
 Well (Farm) No. One Serial No. _____
 Elevation (Spirit Level) 708'
 Quadrangle West Union 15' C Shirley 7 1/2'
 County Tyler District Centerville
 Engineer Robert X. Judd
 Engineer's Registration No. 0459
 File No. _____ Drawing No. _____
 Date 12-19-73 Scale 1" = 200'

STATE OF WEST VIRGINIA
 DEPARTMENT OF MINES
 OIL AND GAS DIVISION
 CHARLESTON

WELL LOCATION MAP
 FILE NO. Ty1-955-A

+ Denotes location of well on United States Topographic Maps, scale 1 to 62,500 latitude and longitude lines being represented by border lines as shown.

- Denotes one inch spaces on border line of original tracing.

47 095 AUG 2 1974