

COMPLETE WELL INSPECTION FORM

ASSIGNED API NUMBER 47- _____ GPS DATE _____

API NUMBER 47- 101-00067 _____ WELL OPERATOR Cabot _____

FARM NAME Preston Carroll _____ WELL NUMBER 1 _____

A. THE ACCESS ROAD MEETS ALL REQUIREMENTS? (22-6-30, 35CSR-4-16)

- 1. CULVERTS PROPERLY SIZED AND SPACED YES NO N/A
- 2. DISSIPATING DEVICES YES NO N/A
- 3. PROPERLY MAINTAINED YES NO N/A
- 4. DIVERSION DITCHES IN PLACE YES NO N/A

B. THE WELL AND LOCATION ARE PROPERLY EQUIPPED AND RECLAIMED? (22-6-30, 22-6-6, 35CSR-4-16)

- 1. API NUMBER YES NO N/A
- 2. DIVERSION DITCHES YES NO N/A
- 3. ALL DISTURBED AREAS RECLAIMED YES NO N/A
- 4. IS SITE FREE OF OIL, GAS AND SALT WATER LEAKS YES NO N/A
- 5. IS WELL PRODUCING YES NO N/A
- 6. PRODUCTION REPORTS BEEN FILED YES NO N/A

C. DOES THE SPILL PREVENTION MEET ALL REQUIREMENTS?(22-6-7, 35CSR1-7, 35CSR-4-11 TO 17)

- 1. ARE TANKS PROPERLY EQUIPPED WITH THE FOLLOWING:
 - A. SECONDARY CONTAINMENT YES NO N/A
 - B. VALVES YES NO N/A
 - C. EQUALIZING LINES YES NO N/A
- 2. ARE SECONDARY CONTAINMENT STRUCTURES PROPERLY CONSTRUCTED:
 - A. IMPERVIOUS YES NO N/A
 - B. DIKES PROPERLY SIZED YES NO N/A
 - C. SURFACE WATER PROPERLY DRAINED YES NO N/A
 - D. VALVES INSTALLED ON DIKE DRAINS YES NO N/A
 - E. DIKE DRAIN VALVES CLOSED YES NO N/A

D. IS SALT WATER BEING PROPERLY DISPOSED OF? (22-6-7) YES NO N/A

E. WAS THIS INSPECTION ROUTINE? YES NO
SPECIFY (COMPLAINT, RANDOM, ETC.) _____

F. IS THIS WELL PART OF A SECONDARY RECOVERY FIELD? YES NO

G. WERE ENFORCEMENT ACTIONS TAKEN AS A RESULT OF THIS INSPECTION? YES NO
SPECIFY (VIOLATION, WARNING LETTER) _____

COMMENTS: well is shut in but it is not plugged.

DATE 11-19-19 _____

INSPECTOR *Danny Mullins* _____