

Cancel


State of West Virginia
Division of Environmental Protection
Section of Oil and Gas

WELL PLUGGING INSPECTION & RELEASE FORM

Farm name: CASWALL, ROBERT DEAN JR. Operator Well No.: GARNER 5111

LOCATION: Elevation: 1,273.00 Quadrangle: HUNDRED
District: CHURCH County: WETZEL

Company: EQUITRANS, L.P.
3500 PARK LANE
PITTSBURGH, PA



PLUGGING COMMENCED _____ VERBAL PERMISSION ON _____
PLUGGING COMPLETED _____

1. IS COAL BEING MINED IN THE AREA? YES NO
2. WERE CEMENT AND GEL MIXED AND USED IN ACCORDANCE WITH ACCEPTED INDUSTRY STANDARDS?
 - A. BOTTOM HOLE PLUGGED YES NO
 - B. 100' PLUGS YES NO
 - C. LATEX PLUGS USED FOR H2S GAS YES NO
 - D. PROPER PLUGS THROUGH COAL SEAMS YES NO
 - E. PROPER PLUGS SET TO PROTECT FRESHWATER YES NO
 - F. PROPER AMOUNT OF GEL USED TO DISPLACE PLUGS YES NO

TYPE	FROM	TO	PIPE REMOVED

3. WERE ALL CHANGES APPROVED BY INSPECTOR? YES NO
4. WAS THE EQUIPMENT USED FOR PULLING CASING PROPERLY SIZED AND RIGGED TO PULL 150% OF THE HEAVIEST STRING OF PIPE EXPECTED TO BE PULLED? YES NO
5. DID THE OPERATOR GIVE THE INSPECTOR PROPER NOTICE? YES NO
6. WERE ACCURATE PLUGGING RECORDS KEPT BY THE OPERATOR? YES NO
7. WAS A PROPER MONUMENT SET WITH API NUMBER ATTACHED? YES NO
8. DID WELL SITE AND ACCESS ROAD MEET THE FOLLOWING RECLAMATION REQUIREMENTS?

A. RECLAIMED	YES NO	B. FENCES REPLACED	YES NO
C. MULCHED	YES NO	D. PROPER DRAINAGE	YES NO
E. SEEDED	YES NO	F. ALL EQUIPMENT REMOVED	YES NO

7/26/99
DATE RELEASED

Kandel Meich
INSPECTOR'S SIGNATURE

RECORD ALL VISITS TO THIS WELL ON BACK

Cancel